## SELLER'S PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between the Seller and any buyer. The Seller authorizes the Listing Broker in this transaction to disclose the information in this statement to other real estate licensees and to prospective buyers of this property. The Seller agrees to notify the Listing Broker promptly of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

NOTE: DO NOT LEAVE ANY QUESTIONS BLANK. WRITE N/A (NOT APPLICABLE) OR UNKNOWN IF NEEDED. 884 Millvale Road

PROPERTY LOCATED AT: Bucksport, ME 04416

		SECTION	I. WATER S	SUPPLY		
THE OF GLOTTE						
TYPE OF SYSTEM				Seasonal		
MALEUNGTIONS	■ Drilled			Other		
MALFUNCTIONS	: Are you aware of or have					
	· – .	□ No □ N/A ▼ No □ Unknown		uantity:	Li Yes Lai No	) 🗀 Unknown
WATER TEST:	If YES to any question, p Have you had the water to	iease expiain in the co	mment section bei	ow or with attachment.	▼ Yes □ No	1
WAIER IESI:	IF YES: Date of most red					
	To your knowledge, have					
	IF YES, are test results a					
	What steps were taken to					,
• IF PRIVATE:	what steps were taken to	remedy the problem?				
	LATION: Location: 100	least of CE	orner of h	NIGO		
INSTALI						
	Installed BY: <b>Hanscom</b> What is the source of you	r information: Coll	or			
USE:	M 1 CD					
OSE.	Does system supply wate	r for more than one ho	nisehold?			In D. Halmarra
COMMENTS: PI	mp replaced afte:					O LI UIIKIIOWII
COMMENTS: Fu	mp repraced arce.	L TIGHTHING BO	LIKE ZUIS			
	S	ECTION II. W	ASTE WATI	ER DISPOSAL		
TYPE OF GYGTEN					. I I I I I I I I I I I I I I I I I I I	
TYPE OF SYSTEM		Private  Quasi-Pi	ublic		Unknown	
• IF PUBLIC OR					_	
	experienced any problems					Yes 📙 No
-	s were taken to remedy the	problem?				
• IF PRIVATE:	<b>▼</b> 0 4 7 1			Пол		
TANK:	_	Holding Tank				
Tank Size		☐ Metal		Other:		
Tank Type	e:					
Have you	Pumped:experienced any malfunction	Nai ons?	ne of Company Pt	imping rank:		Yes 🗓 No
If yes, give	e the date and describe the	oroblem:				103 - 110
	st Servicing of tank: _20					
LEACH F	IELD:				🛛 Yes 🗖 No	☐ Unknown
	ocation: Just south					
Date of ins	stallation of leach field:	L990	Installe	ed by: Carl Hansco	m.	
Date of La	st Servicing of leach field:	N/A	Nar	ne of Company Servicing	leach field:	
Have you	experienced any malfunction	ons?				Yes 🛮 No
If yes, give	e the date and describe the	problem & what steps	were taken to rem	edy:		
IF YES, is	ecords of the septic system it available? <b>Yes</b>	design indicating the	e number of bedro	oms the system was design	gned for? 🛚	Yes $\square$ No
SOURCE OF INFO	ORMATION: HHE-200					
COMMENTS:						
	ATED IN A SHORELAND					
Is System located in	n a Coastal Shoreland Zone					Unknown
	Page 1 of 3 - SPD But	ıyer(s) Initials		Seller(s) Initials		<u></u>
Maine Real Estate Brokerage George MacLeod	e, P.O. Box 306 Bucksport, ME 04416			Phone: (207)944-8771 er. Michigan 48026 www.zipLogix	Fax:	Steve Norton

FROFERTT LOCATED AT 604	MIIIVale Road, Buck	sport, ME 04410				
	SECTION III. HE	ATING SYSTEM	(S)/SOURCES(	S)		
Hasting System (s)/Saumas(s)	CVCTEM 1	SYSTEM 2	SYSTEM 3		CVCTEM	T 4
Heating System(s)/Source(s) TYPE(S)	SYSTEM 1 Wood stove	HW/Radiators	Heat Exchan	gor	SYSTEM Electr:	
Age of system(s)/source(s)	New	2011	1990	iger	1990	IC BB
Name of company that services	INCW	Spring Brook	N/A		N/A	
system(s)/source(s)						
Date of most recent service call		12/31/2013				
Annual consumption per system/	3.25 cord	200 gal propane	0		200 KW	/ year
source (i.e., gallons, kilowatt hours, cord(s))						
Malfunction per system(s)/	N/A	N/A	N/A		N/A	
source(s) within past 2 years						
Other pertinent information	<u> </u>		_		<u> </u>	
Is there an oil supply line? ☐ Yes ☐ Chimney(s): ☐ Yes ☐ No If yes Is more than one heat source vented Has chimney been inspected? ☐ Y	s, lined: $\square$ Yes $\square$ No $\square$ through one flue? $\square$ Yes	☐ Unknown Last Cle  ■ No ☐ Unknown	eaned: Had a ch	— imney fire:	☐ Yes 🏻	No  Unknown
COMMENTS: Chimney clea						
	SECTION IV.	. HAZARDOUS I	MATERIAL			
The licensee is disclosing that the So						
A. UNDERGROUND STORAGE Are there now, or have there ev IF YES: Are tanks in current u IF NO above: How long h	TANKS - Current or previously rer been, any underground stage? Yes No ave tank(s) been out of servi	ously existing: orage tanks on your propo Unknown ce?	•			X Unknown
What materials are, or were, sto	ored in the tank(s)?					
Age of tank(s):	Size of tank(s):					
Location: Have you experienced any prol	alams such as laskaga?					
Are tanks registered with the I	Dent of Environmental Prote	ection?		□ Ves	Пиог	7 Unknown
If tanks are no longer in use, h						
Comments:				—		_
<ul><li>ASBESTOS - Current or previous</li><li>as insulation on the heating</li></ul>	•			□ Vas	IVI No. [	7 Unknown
	Yes No Unknown		e roofing shingles?			
	Tes X No Unknown		:			Unknown
IF YES: Source of Information			•			
COMMENTS:	<u></u>					
C. RADON/AIR - Current or prev						
Has the property been tested?						Unknown
IF YES: Date:	By:By:	4:-1 -4 4-1	0			
Has the property been tested si	ii applicable, what	remediai steps were takei	n?		□ N- I	
Are test results available?	☐ Yes ☐ No Re	sults & Comments:				
D. RADON/WATER - Current or					1990 s.r. (	<b>-</b>
Has the property been tested?						■ Unknown
IF YES: Date:Results:	By: If applicable, What	remedial stens were take	n?			
Has the property been tested si	nce remedial stens?	remediai steps were taker		□ Yes	Поп	7 Unknown
Are test results available?		sults & Comments:				_ Clikilowii
E. LEAD-BASED PAINT/PAINT						n homes
constructed prior to 1978)  Is there now or has there ever be	neen lead-based naint and/or	lead-based paint bazards	on the property?	□ Yes	No F	Unknown
is there now of has there ever t	con read-based paint and/or	read-based paint nazards	on the property:			ossible due to age
IF YES, describe location and	the basis for the determination	on:		Onki		
Do you know of any records or IF YES, describe:	reports pertaining to such le	ead-based paint or lead-ba	sed paint hazards:	☐ Yes	X No	
					-	
Are you aware of any cracking	, peeling or flaking paint?			☐ Yes	X No	

Seller(s) Initials

Page 2 of 3 - SPD Buyer(s) Initials \_\_\_\_\_

COMMENTS:

2015

PROPERTY LOCATED AT 884 Millvale Road, Bucksport, M	E 04416
F. OTHER HAZARDOUS MATERIALS - Current or previously existing:  TOXIC MATERIAL:  Yes No Unknown  LAND FILL:  Yes No Unknown  RADIOACTIVE MATERIAL:  Yes No Unknown  Unknown  Buyers are encouraged to seek information from professionals regarding any	OTHER:
SECTION V. GENER	
Is the property subject to or have the benefit of any encroachments, easement private road/homeowner associations or restrictive covenants?	ts, rights-of-way, leases, rights of first refusal, life estates, private way,  Yes No Unknown  The from abutter for utility line  luding but not limited to: Tree Growth, Open Space and Farmland,
IF YES: Explain: Tree Growth, Homestead Exemption	1 tes   No   Ulikliowii
Is this house currently covered by a flood insurance policy?	☐ Yes 🛮 No 🗖 Unknown
• Leased Equipment (e.g., propane tank, hot water heater, satellite dish): T	ype: No
Year Principal Structure Built: 1990	What year did Seller acquire property? 1989
• Roof: Year Built - Structure: 1990 Water, moisture or leakage: No Comments: N/A	Year Shingles/Other Installed: 2012
• Foundation/Basement: Sump Pump: ☐ Yes No ☐ Water, moisture or leakage since you owned the property: ☐ Yes X No Knowledge of prior water, moisture or leakage: ☐ Yes X No ☐	Unknown Comments:  O Unknown Comments: cellar drain backed up once Unknown Comments:
Mold: Has the property ever been tested for mold? ☐ Yes ☒ No ☐	Unknown If YES, are test results available?   Yes  No
Electrical:    Fuses	Unknown
<ul> <li>Has all or a portion of the property been surveyed?</li></ul>	n Modular - ☐ Yes 🗶 No ☐ Unknown
Seller shall be responsible and liable for any failure to provide known inform ATTACHMENTS EXPLAINING CURRENT PROBLEMS, PAST REPOSICLOSURE:  Yes No  SECTION VI. ADDITION Driveway paved 2015	PAIRS OR ADDITIONAL INFORMATION IN ANY SECTION IN
House painted 2013 Electric entrance updated with transfer switch	for emergency generator 2014
As Sellers, we have provided the above information and represent that all infequipment, unless otherwise noted on this form, are in operational condition. Neither Seller nor any Broker makes any representations as to the applicability.	
federal or any other, including but not limited to fire, life safety, building, ele	
GEV V ED	June 30, 2017
SELLER Stephen A. Norton	DATE
SELLER	DATE
I/We have read and received a copy of this disclosure, the arsenic in wood seek information from qualified professionals if I/we have questions or conce	
BUYER	DATE
BUYER	DATE



**Maine Association of REALTORS®/Copyright © 2015.**All Rights Reserved. Revised 2015. Page 3 of 3 - SPD

