Maine Real Estate Brokerage, P.O. Box 306 Bucksport ME 04416

George MacLeod

PROPERTY DISCLOSURE

Under Maine Law, certain information must be made available to buyers prior to or during preparation of an offer. This statement has been prepared to assist prospective buyers in evaluating this property. This disclosure is not a warranty of the condition of the property and is not part of any contract between Seller and any Buyer. Seller authorizes the disclosure of the information in this statement to real estate licensees and to prospective buyers of this property. The Seller agrees to provide prompt notice of any changes in the information and this form will be appropriately changed with an amendment date. Inspections are highly recommended.

DO NOT LEAVE ANY QUESTIONS BLANK. STRIKE, WRITE N/A OR UNKNOWN IF NEEDED.

	SECTION I — WATER SUPPLY		
TYPE OF SYSTE	EM: Public X Private Seasonal Unknown Drilled Dug Other		
MALFUNCTION	IS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water system?		
	Pump (if any):		
	Quantity: Yes X No Unknown		
	Quality: Yes X No Unknown		
	If Yes to any question, please explain in the comment section below or with attachment.		
WATER TEST:	Have you had the water tested?		
	If Yes, Date of most recent test: <u>08/03/2022</u> Are test results available? X Yes No		
	To your knowledge, have any test results ever been reported as unsatisfactory or satisfactory with notation?		
	If Yes, are test results available?		
	What steps were taken to remedy the problem? Radon mitigation system		
	trike Section if Not Applicable):		
INSTALLAT	TION: Location: On left side of driveway about 180' from house		
	Installed by: Williams and Taplin		
	Date of Installation: 1989		
USE:	Number of persons currently using system: 3		
	Does system supply water for more than one household? Yes X No Unknown		
Comments: Non	e		
Course of Section	n I information: Seller		
Source of Section	HA DO		
Buyer Initials	Page 1 of 8 Seller Initials		
	Phin and Hanna		

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

Phone: 2079448771

SECTION II — WASTE WATER DISPOSAL
TYPE OF SYSTEM: Public Private Quasi-Public Unknown
F PUBLIC OR QUASI-PUBLIC (Strike Section if Not Applicable): Have you had the sewer line inspected? No
If Yes, what results:
Have you experienced any problems such as line or other malfunctions?
What steps were taken to remedy the problem?
IF PRIVATE (Strike Section if Not Applicable):
Tank: X Septic Tank
Talik Size. 500 Garion 7 Total Cothorn
OR Unknown
Location: Behind deck Date installed: 08/01/1989 Date last pumped: unavailable Name of pumping company: N/A
Have you experienced any malfunctions?
If Yes, give the date and describe the problem: Cracked tank cover. Seller replaced and resealed
If Yes, give the date and describe the problem.
Date of last servicing of tank: May 2022 Name of company servicing tank: Seller
Leach Field: X Yes No Unknown
If Yes, Location: 14' from tank Date of installation of leach field: 08/01/1988 Installed by: Unavailable
Date of installation of leach field: 06/01/1966 Installation of leach field: N/A Company servicing leach field: N/A
Have you experienced any malfunctions?
If Yes, give the date and describe the problem and what steps were taken to remedy: N/A
If Yes, give the date and describe the problem and what steps were taken to remark a series were
Do you have records of the design indicating the # of bedrooms the system was designed for? X Yes No
If Voc are they available?
Is System located in a Shoreland Zone?
Comments: None
Source of Section II information: Seller, public records
DP 1h
Buyer Initials Page 2 of 8 Seller Initials

SEC	TION III – HEATIN	NG SYSTEM(S)/HEA	TING SOURCE(S)	
EXCENSION DEFINITION OF THE PERSON OF THE	SYSTEM 1	SYSTEM 2	SYSTEM 3	SYSTEM 4
Heating System(s) or Source(s)	Oil / Wood / FHA	Wood stove	V.U.Z.	
TYPE(S) of System Age of system(s) or source(s)	1989	1989		
TYPE(S) of Fuel	Oil / Wood	Wood	STERNING TO THE STERNING THE STERNING TO THE STERNING THE S	
Annual consumption per system	On / Wood			
or source (i.e., gallons, kilowatt	Avg 350 gal / 4 cord wood	Included in system 1 data		
hours, cords)				
Name of company that services				
system(s) or source(s)	Dead River	N/A		
Date of most recent service call		N/A		
Malfunctions per system(s) or		and the second s		
source(s) within past 2 years		None		
Other pertinent information	Oil and wood burners share	None		
	same chimney flue			
Are there fuel supply line	207		x Yes	No Unknown
Are there fuel supply line	J3:	••••••	Yes	X No Unknown
Are any buried?				
Are all sleeved?				No Unknown
Chimney(s):			<u>X</u> Yes	No
If Yes, are they li	ined:		X Yes	No Unknown
Is more than one hea	t source vented throug	h one flue?	X Yes	No Unknown
				X No Unknown
				X No Unknown
If Yes, date:				
25000 - 250	cleaned: Fall 2023	F=112024 DC		
Direct/Power Vent(s):			Yes	X No Unknown
Has vent(s) been	inspected?		Yes	No Unknown
	mspected:			
Comments: None Source of Section III int	formation: Saller		NAME OF THE OWNER OWNER OF THE OWNER OWNE	
Source of Section III III		ZADBOUG M	ATERIAL	
		/ — HAZARDOUS M		
The licensee is disclosing	ng that the Seller is ma	king representations co	ntamed herem.	een anv undergroung
A. UNDERGROUNI				I No W Linkmour
storage tanks on the property? Yes No X Unknown If Yes, are tanks in current use? No Unknown				
If Yes, are tanks in curr	ent use?		Yes	No Unknown
10 ms homer in use how	tone have they been o	out of service?		No Unknown
-If tanks are no longer in	r use, have tanks been	abandoned according t	o DEP? Yes	No Unknown
Are tanks registered wi	th DEP?			
Age of tank(s):		Size of tank(s):	CONTROL OF THE PROPERTY OF THE	
Location.			11.	50
			1 1 7	131/
Buyer Initials		Page 3 of 8	Seller Initials	PL

PROPERTY LOCATED AT: 53 Winkumpaugh Road, Orland, Me 04472		
What materials are, or were, stored in the tank(s)?		ANNE COLUMNATOR DE LA MANDIO CON ESTADOS EN ESTADOS ENTENDADOS EN ESTADOS ENTENDADOS EN ESTADOS ENTENDADOS EN ESTADOS ENTENDADOS EN ESTADOS ENTENDADOS ENT
Have you experienced any problems such as leakage:	Ves	No Unknown
Comments: None		
Source of information: Seller		
B. ASBESTOS — Is there now or has there been asbestos:		
As insulation on the heating system pipes or duct work?	Yes	X No Unknown
In the ceilings?	Yes	X No Unknown
In the siding?	Yes	X No Unknown
In the roofing shingles?	Yes	X No Unknown
In flooring tiles?	Yes	X No Unknown
Other:	Yes	X No Unknown
Comments: None		Company of the second s
Source of information: Seller		
C. RADON/AIR - Current or previously existing:		
Has the property been tested?	X Yes	No Unknown
If Yes: Date: May 2022 By: Norlen's Water		
Results: High air radon concentrations		
If applicable, what remedial steps were taken? Remediation system insta	illed	
Has the property been tested since remedial steps?	X Yes	No Unknown
Are test results available?	X Yes	☐ No
Results/Comments: Acceptable		
Source of information: Seller		
D. RADON/WATER - Current or previously existing:		_
Has the property been tested?	X Yes	No Unknown
If Yes: Date: May 2022 By: Norlen's Water		
Results: High water radon concentrations		
If applicable, what remedial steps were taken? Remediation system inst	alled	
Has the property been tested since remedial steps?	X Yes	No Unknown
Are test results available?	X Yes	☐ No
Results/Comments: Acceptable		
Source of information: Seller		
E. METHAMPHETAMINE - Current or previously existing:	Yes	X No Unknown
Comments: None		
Source of information: Seller		

1 1	vailable?			☐ No
Results/Commen	nts: Acceptable	wine with a second control of the second con		
Source of inform E. METHAMI Comments: Non	PHETAMINE - Current or p	reviously existing:	Yes	X No Unknown
Source of inform	nation: Seller			
Buyer Initials	Produced with Lone Wolf Transactions (zipForm	Page 4 of 8 Edition) 717 N Harwood St, Suite 2200	Seller Initials P	Phin and Hannah

Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 75201 www.lwolf.com

PROPERTY LOCATED AT: 53 Winkumpaugh Road, Orland, Me 04472

SECTION VI - FLOOD HAZARD

For the purposes of this section, Maine law defines "flood" as follows:

- (1) A general and temporary condition of partial or complete inundation of normally dry areas from:(a) The overflow of inland or tidal waters; or (b) The unusual and rapid accumulation or runoff of surface waters from any source; or
- (2) The collapse or subsidence of land along the shore of a lake or other body of water as a result of erosion or undermining caused by waves or currents of water exceeding anticipated cyclical levels or suddenly caused by an unusually high water level in a natural body of water, accompanied by a severe storm or by an unanticipated force of nature, such as a flash flood or an abnormal tidal surge, or by some similarly unusual and unforeseeable event that results in flooding as described in subparagraph (1), division (a).

For purposes of this section, Maine law defines "area of special flood hazard" as land in a floodplain having 1% or greater chance of flooding in any given year, as identified in the effective federal flood insurance study and corresponding flood insurance rate maps.

During the time the seller has owned the property:		
Have any flood events affected the property?	Yes	X No Unknown
If Yes, explain:		
Have any flood events affected a structure on the property?	Yes	X No Unknown
If Yes, explain:		
Has any flood-related damage to a structure occurred on the property	? Yes	X No Unknown
If Yes, explain:		
Has there been any flood insurance claims filed for a structure on the property?	Yes	🛛 No 🗌 Unknown
If Yes, indicate the dates of each claim:		
Has there been any past disaster-related aid provided related to the provided	roperty	
or a structure on the property from federal, state or local sources for purposes of flood recovery?	Yes	X No Unknown
If Yes, indicate the date of each payment:		
Is the property currently located wholly or partially within an area of		
flood hazard mapped on the effective flood insurance rate map issue	d by the	
Federal Emergency Management Agency on or after March 4, 2002	? Yes	X No Unknown
If yes, what is the federally designated flood zone for the property	y indicated on that f	lood insurance rate map?
Relevant Panel Number:	Year:	(Attach a copy)
Comments: None		200
Source of Section VI information: Seller		
Buyer Initials Page 6 of 8	Seller Initials	W

SECTION VII — GENERAL INFORMATI	ON	
Are there any tax exemptions or reductions for this property for any reason in		
Tree Growth, Open Space and Farmland, Veteran's, Homestead Exemption, Blir		
	X Yes	No Unknown
If Yes, explain: Homestead		
Is a Forest Management and Harvest Plan available?	Yes	X No Unknown
Equipment leased or not owned (including but not limited to, propane tan	k, hot wat	er heater, satellite dish
water filtration system, photovoltaics, wind turbines): Type: None		
Year Principal Structure Built: 1989		Ti .
What year did Seller acquire property? 1971 2022		
Roof: Year Shingles/Other Installed: 2022		
Water, moisture or leakage: None		
Comments: None		
Foundation/Basement:		
Is there a Sump Pump?	Yes	X No Unknow
Water, moisture or leakage since you owned the property:	Yes	X No Unknow
Prior water, moisture or leakage?	Yes	No X Unknow
Comments: None		
Mold: Has the property ever been tested for mold?	Yes	X No Unknow
If Yes, are test results available?	Yes	☐ No
Comments: None		
Electrical: Fuses X Circuit Breaker Other:		Unknow
Comments: 200 amps		
Has all or a portion of the property been surveyed?	Yes	X No Unknow
If Yes, is the survey available?	Yes	No Unknow
Manufactured Housing – Is the residence a:		-4- SDR
Mobile Home	Yes	X No Unknow
Modular	Yes	X No Unknow
Known defects or hazardous materials caused by insect or animal infestation	inside or o	
	Yes	X No Unknow
Comments: None		
KNOWN MATERIAL DEFECTS about Physical Condition and/or value or	f Property,	including those that m
have an adverse impact on health/safety: None		
Comments: None		
Source of Section VII information: Seller		
Buyer Initials Page 7 of 8 Seller In	nitials <u>M</u>	
Produced with Lone Wolf Transactions (zipForm Edition) 717 N Harwood St, Suite 2200, Dallas, TX 752	01 www.lwolf.com	Phin and Hannah

SECTIO	ON VIII – ADDITIO	NAL INFORMA	TION
		=	
None			
		www.co.co.co.co.co.co.co.co.co.co.co.co.co.	
ATTACHMENTS EXPLAINING O	CURRENT PROBLEM ON IN DISCLOSURE:	IS, PAST REPAIR	S OR ADDITIONAL Yes X No
defects to the Buyer.			ormation regarding known material
of any sort, whether state, municipal electrical or plumbing.	l, federal or any other,	including but not	by of, or compliance with, any codes limited to fire, life safety, building,
As Sellers, we have provided the a our knowledge, all systems and equ	bove information and a lipment, unless otherwise	represent that all it ise noted on this fo	nformation is correct. To the best of orm, are in operational condition.
Phin Pake	10/16/24	SELLER	DATE
SELLER	DATE	SELLER	22
Phineas Peake	(0/10/100		
Hannah 9	PATE	SELLER	DATE
SELLER	DATE	SELLER	
Hannah Johnson			
brochure, and understand that I/we	copy of this disclosure e should seek informat	, the arsenic in w ion from qualified	ood fact sheet, the arsenic in water professionals if I/we have questions
or concerns.			
BUYER	DATE	BUYER	DATE
DINER	DATE	BUYER	DATE
BUYER	Dill		

Page 8 of 8

